



Laboratory Audit Procedure

The OSHA/PESH Laboratory Safety Standard (29CFR1910.1450) requires the University to develop and implement a Chemical Hygiene Plan to protect laboratory employees from occupational hazards in laboratories. 29 CFR (1)-2.7 (q)3.2 (z)3.2 (bl)-2.7 (-3.2 (za -0.7 (lp)-0.7 ((r) T) Tc 0.003 Tw (t)-2.4h)2.3 (e)-2211.

All laboratory audits are performed using a computer program (Labcliq). The program requires all PI's to create a username and password to access the program. After completion your audit will be emailed to you thus eliminating the use of paper audit forms and interoffice mail. All violations must be verified as corrected within the program.

All violations noted in the audit MUST be corrected, failure to correct documented safety violations can result in the responsible PI being held liable for “**willfully and knowingly**” allowing a documented safety violation to exist. Because of the seriousness of this liability, a process exists to ensure that all documented safety violations are corrected. The process has Four Stages, with ample time given to PI's to make corrections. Failure to correct safety violations and complete the audit within the given time period will result in the audit process moving to the next successive stage. It is fully anticipated the vast majority of all laboratories will complete the audit process within the first stage.

A two-week extension to correct violations can be granted if the request is received by EH&S (7-2211) prior to the due date. Only one (two) week extension will be granted per lab audit, per semester. In the case of an infrastructure or facilities related violation, submission of a work order to Physical Facilities will qualify as attempting to correct the violation.

Revision date Feb 2024

At any time during the audit process, the responsible faculty member or laboratory personnel may obtain assistance by contacting EH&S at 7-2211.

STAGE 1

After completion of the initial audit, Labcliq will email the audit to the Principal Investigator, Building Administrator and the EHS Inspector. The PI will be given 10 days from the audit date (as noted on the audit) to correct violations and then verify the corrections in the program. Depending on the gravity of the violations, a follow up audit may occur. Failure to correct and verify all violations within 10 days will result in the process moving to stage 2.

STAGE 2

If the safety violations have not been corrected and verified within 10 days, a reminder email will be sent to the PI. The PI will be given 5 days to correct and verify all violations and notify EH&S at (7-2211) of completion. A follow up audit may occur. Failure to meet these requirements will result in the process moving to stage 3.

STAGE 3

If by this time all safety violations have not been corrected, the violations will be escalated to the 3rd tier. A second reminder with stricter verbiage will automatically be sent to the PI with copies to the Dept. Chair and Lab Safety Manager. The PI will have 5 days to correct and verify all noted violations.